




HANSA

Installation and maintenance guide

5242 2263



EN 817
50 - 1000 kPa
0.1 l/s (300 kPa w/Controller)
max. +70°C



mpi.hansa.com/52422263

5242 2267



EN 817
50 - 1000 kPa
0.1 l/s (300 kPa w/Controller)
max. +70°C










mpi.hansa.com/52372267








5268 2267

EN 817
50 - 1000 kPa
0.1 l/s (300 kPa w/Controller)
max. +70°C




mpi.hansa.com/52682267





1









1







max.
1600 kPa



2








2












2.5








②








②







cleaning.hansa.com