




Spare Parts / Ersatzteile / Pièces de recharge / Pezzi di Ricambio / Piezas de requesto /
Parte de reposição / Reserveonderdelen / Reservdelar / Reservedeler / Varaosat /
Vraosat / Varahlutir / Ανταλλακτικά / Yedek Parçalar / Náhradní díly / Náhradné diely /
Nadomestni deli / Резервни части / Запчасти / Części Zapasowe / Pieśe de schimb
/ Rendelhető alkatrészek / Запасні частини / Reservni delovi / Резервни делови /
Резервни делови / Atsarginių dalių / Tellitavad varuosad / Rezervju daļu

1 = A 963 131 NU
2 = A 963 132 NU
3 = A 963 146 NU






A




DIN EN 1717
HD

A 3318 AA
F 1091 AA


9a



9a



IEC 60364







9b






B1

B2



IEC 60364

9c



Ideal Standard International NV
Corporate Village - Gent Building
Da Vincilaan 2
1935 Zaventem
Belgium

www.idealstandardinternational.com





EASY BOX
A 1000 NU

Ideal Standard

1020 / A 866 090 40

Made in Germany



* 9a

